



LAND ROVER

LAND ROVER

 Code 

0-9

12 L 632-634

14TCIE 632

17H 634

18K16 632

200TDi 634

21 L 636

23 L 634

25 K4F 636

300TDi 636

I

i6 636

T

Td5 632

 Code 

 Code 

 Code 

 Code 

 Code 

 Code 

 Code 

LAND ROVER						
Ltr.						
1,8 18K16	86-88 kW (117-120 PS)	FREELANDER 16V	02/98→	D37245-00 ⑫ B37246-00 ⑬	H50497-10 LVB500190 	T50497-00 WAN2293L (10x)
2,0 14TCIE	72 kW (98 PS)	FREELANDER DI	02/98-11/00	S36055-00 ⑫ ⑬ D36055-00 ⑫ 	H01312-00 LVB101820L 1,45 mm 1 H11312-10 LVB101830L 1,55 mm 2 H21312-20 1,65 mm 3	
2,5 Td5	102 kW (139 PS)	DISCOVERY Td5	01/99→	D36884-00 ⑫ → 1A736339 D36885-00 ⑫ → 2A736340→ B36884-00 ⑬	H08014-00 LVB000240 86 ∅ 1,2 mm 2 H18014-10 LVB000250 86 ∅ 1,27 mm 1 H28014-20 LVB000260 86 ∅ 1,35 mm 3	T08014-00 ERR5384 (12x)
2,5 12 L	83 kW (113 PS)	DISCOVERY TDI	08/96→	D36117-00 ⑫ STC362 	H37879-30 ERR7154 92 ∅ 1,71 mm 0 	T07879-00 ETC8808 (4x) +ETC8809 (10x) +ETC8810 (4x)

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

X53289-01 LVP100630L 		X89969-01 LKJ101110L 	X82388-01 LKG100551 		P77395-01 N ← 30x40x7 FPM P77697-01 N → LUC100220L 30x40x7 A SL LD
X53700-01 LVP100400 			X81655-01 ⚠ WCM100480 		P77126-01 K ← WZX1915 35x45x7 RD FPM P77397-01 K →
		X52283-01 ⑦ LKJ100790 			
X83088-01 ERR7094 → 1A736339	N92743-00 LJQ100940 (10x) P76839-00 LJQ100940	X89134-01 LKJ000010 	X81515-01 LKG100470 X82370-01 ⚠ ESR3737 	X54795-01 LVF500040 	P77399-01 K ← ERR5992 50x65x8 AB SL RD FPM
X83089-01 LVP000020 → 2A736340→					
X53646-01 NBR 			X52550-01 ⑦ 		P76175-01 K ← ADU8891 48,6x63,65x9,2 NBR P76400-01 K → ERR2532 100x120x12 LD P76111-01 N 13510-V7200 40x52x7 RD FPM



LAND ROVER						
Ltr.						
2,5 12 L 200TDi	83-90 kW (113-122 PS) DEFENDER TDI DISCOVERY TDI	09/89→	D36117-00 STC362 	H01826-00 LVB5000200 1,3 mm MLS H11826-10 LVB500210 1,4 mm MLS H21826-20 LVB500220 1,5 mm MLS H31826-30 LVB500230 1,6 mm MLS H07879-00 ERR5261 1,42 mm 1 H17879-10 ERR5262 1,52 mm 2 H27879-20 ERR5263 1,62 mm 3 H37879-30 ERR7154 1,71 mm 	T07879-00 ETC8808 (4x) +ETC8809 (10x) +ETC8810 (4x) 	
2,5 17H 23 L	61-86 kW (83-117 PS) DEFENDER 90/110	09/85-12/94	S30103-00 ⑫ ⑬ 501677 D30103-00 ⑫ B30103-00 ⑬ RTC809	H02281-00 GEG338 		

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



X53646-01 NBR 	N90700-00 ETC8663 (x8) P76636-00 ETC8663 8x	X52550-01 ⑦ 	731414 	P76175-01 K ← ADU8891 48,6x63,65x9,2 NBR P76400-01 K → ERR2532 100x120x12 LD P76111-01 N 13510-V7200 40x52x7 RD FPM	
X03838-01 GEG431 Kork 	N90790-00 554727(x4)+ P76509-00 554728 P76510-00 554727 4x 4x	X02265-01 ⑦ GEG723 X02284-01 ⑦ 274171 	X03755-01 GEG537 	P76175-01 K ← ADU8891 48,6x63,65x9,2 NBR P76272-01 K → 523240 63,5x82,5x7,9 LD FPM	



LAND ROVER						
Ltr.						
2,5 21 L 300TDi	83-90 kW (113-122 PS) DEFENDER TDI DISCOVERY TDI	09/89→	S32149-00 ¹² ¹³ D32149-00 ¹² STC2802 B32149-00 ¹³ STC2801	H01826-00 LVB5000200 1,3 mm MLS H11826-10 LVB500210 1,4 mm MLS H21826-20 LVB500220 1,5 mm MLS H31826-30 LVB500230 1,6 mm MLS H07879-00 ERR5261 1,42 mm 1 H17879-10 ERR5262 1,52 mm 2 H27879-20 ERR5263 1,62 mm 3 H37879-30 ERR7154 1,71 mm 	T01826-00 ERR1939 (10x) +ETC8808 (4x)	
2,5 25 K4F	130 kW (177 PS) FREELANDER V6	11/00→	D36106-00 ¹² B36106-00 ¹³	H80102-00 2x LVB101630L 	T40360-00 2x 	
3,2 i6	170 kW (231 PS) FREELANDER 2	10/06→	D38089-00 ¹² B38133-00 ¹³	H40376-00 LR006664 84,85 \varnothing MLS 	T50037-00 LR002553 (14x) 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



X53207-01 ERR2409 NBR 	N90700-00 ETC8663 (x8) P76636-00 ETC8663 8x	X51509-01 ⁷ ERR3785 	X54675-01 731414 	P76458-01 K ← 47x62x9 RD FPM P77400-01 K → LUF100430 FPM P76117-01 N 40x56x7 RD	
X83157-01 2x LVP100470L 	N95980-00 LJB100350L P76632-00 LJB100350L 24x	X85000-01 2x LKJ100680L 	X52551-01 2x LKG100290L 	P77461-01 K ← LQX100070L 32x45x6,8 RD P77462-01 K → LUF100300L	
V38118-00 LR001808 (6x) +LR001978 		X89889-01 6x LR001454 	X82354-01 2x LR001455 	P77353-01 K → LR001418 98x118x10 A SL LD	

